

# SCHOOL OF ENGINEERING - BUILDING SAFETY AUDIT - FAULT REPORT SHEET

Please note that building audits provide a periodic overview of safety performance in the school and are supplementary to statutory inspections and other specific safety management procedures.

Building: <b>JUNE</b>		Audited by: <b>D.S. Macgregor / S. Fyfe / M. Zhou</b>	Date: <b>14/8/13</b>	
Room No	Room Function	Description of Fault	Urgent Y/N	Date Resolved
401	CONFERENCE ROOM	FLOOR COVERING TRIP HAZARD	N	
	CONNECTION DOOR JUNE / JWS	EXIT BUTTON FOR DOOR LOCK UNRELIABLE	Y	
3-51	MEZZANINE	SERIOUS RISK OF INJURY FROM SCRAP SURFACE PROTRUDING TITANUM PROTECTIVE LAGGERS - LAGGERS NEEDS REPAIR IN SEVERAL AREAS	Y	
3-51	MEZZANINE	SEVERAL LIMDBOARD BOXES STORING AIR FILTERS TO OPEN TITANUM LAGGERS. ALTERNATIVE STORAGE PARKED SHOULD BE FOUND	Y	
	MEZZANINE	LIGHTING ABOVE PUMPS AT AREA OUT	Y	
	JUNE STAIRCASE	RESPIRATORY EQUIPMENT AUTOMATICALLY E FACE STRIPPED NEEDS SORTED	Y	
3-21	BROWNS / SCRABLE	RELOCATE CONNECTION BLOCK ON FLOOR HOT PLATE TOO NEAR SOLVENTS	Y	14/8/13
3-10	MIXER PRESSURE	ADDITIONAL SUPPORT FOR PROBE STATION LID ADVISED	N	
	CORRIDOR FROM L3 TO L2	ESCAPE DOOR TO COMPUTER SERVICES SHOULD BE CHECKED TO SEE ESCAPE ROUTE	N	