Room no. JWS Level 3 north end R342

FABRIC – General condition - good/ok/needs attention	
Lights	
Heating	
Ventilation	
Floors/floor coverings	
Fire doors, doors and door furniture	
Electrical installation	
Sanitary Fittings	
Washing/Drying facilities	
Windows and window fittings	
Staircases, banisters and hand rails	
Furniture and fittings	
Other	
HOUSEKEEPING – good/ok/needs attention	
Storage of materials	Excessive furniture stored in corridor causing cluttered
	area
Cleanliness	
Hygiene	
Escape routes/passages	
Cable management	
Slipping/tripping hazards	
Electrical Equipment Inspection and	
Testing	
Other	

Room no. JWS Level 4 north end R426

FABRIC – General condition - good/ok/needs attention		
Lights	1 off lamp out in corridor adjacent to R427b. Upgrade of lighting required due to poor illumination of corridor	
Heating		
Ventilation		
Floors/floor coverings	General condition of carpet is very worn and threadbare	
Fire doors, doors and door furniture		
Electrical installation		
Sanitary Fittings		
Washing/Drying facilities		
Windows and window fittings		
Staircases, banisters and hand rails		
Furniture and fittings		
Other		
HOUSEKEEPING – good/ok/needs attention		
Storage of materials		
Cleanliness		
Hygiene		
Escape routes/passages		
Cable management		
Slipping/trippinghazards	Lack of threshold strips resulting in carpet curling up in	
	doorways	
Electrical Equipment Inspection and		
Testing		
Other		

Room no. JWS Level 4 north end public toilet R415

FABRIC – General condition - good/ok/needs attention			
Lights	1 off lamp out		
Heating			
Ventilation			
Floors/floor coverings			
Fire doors, doors and door furniture			
Electrical installation			
Sanitary Fittings	Urinals slow to clear potential blockage. Sink tap loose		
Washing/Drying facilities			
Windows and window fittings			
Staircases, banisters and hand rails			
Furniture and fittings			
Other			
	HOUSEKEEPING – good/ok/needs attention		
Storage of materials			
Cleanliness			
Hygiene			
Escape routes/passages			
Cable management			
Slipping/tripping hazards			
Electrical Equipment Inspection and			
Testing			
Other			

Room no. JWS Level 5 public toilet R519b

FABRIC – General condition - good/ok/needs attention		
Lights		
Heating		
Ventilation		
Floors/floor coverings		
Fire doors, doors and door furniture		
Electrical installation		
Sanitary Fittings	Taps sticking on, potential for flooding (known problem). Urinal water-usage monitor hanging by wire from ceiling. Accessible toilet no personal alarm fitted, inappropriate door furniture, perhaps sliding door not appropriate also	
Washing/Drying facilities		
Windowsand window fittings		
Staircases, banisters and hand rails		
Furniture and fittings		
Other		
HOUSEKEEPING – good/ok/needs attention		
Storage of materials		
Cleanliness		
Hygiene		
Escape routes/passages		
Cable management		
Slipping/trippinghazards		
Electrical Equipment Inspection and		
Testing		
Other		

Room no. JWS Level 5 public toilet R507

FABRIC – General condition - good/ok/needs attention		
Lights	1 off lamp out	
Heating		
Ventilation		
Floors/floor coverings		
Fire doors, doors and door furniture		
Electrical installation		
Sanitary Fittings		
Washing/Drying facilities	Excessively cracked sink.	
	Tiles missing or broken around sink.	
Windows and window fittings		
Staircases, banisters and hand rails		
Furniture and fittings		
Other		
	EPING – good/ok/needs attention	
Storage of materials		
Cleanliness		
Hygiene		
Escape routes/passages		
Cable management		
Slipping/tripping hazards		
Electrical Equipment Inspection and		
Testing		
Other		

Room no. JWS Level 6 side corridor R638

FABRIC – General condition - good/ok/needs attention		
Lights	2 off lightsout adjacent to R607	
Heating		
Ventilation		
Floors/floor coverings	Trip hazard due to broken floor tiles at R607b	
Fire doors, doors and door furniture		
Electrical installation		
Sanitary Fittings		
Washing/Drying facilities		
Windows and window fittings		
Staircases, banisters and hand rails		
Furniture and fittings		
Other		
HOUSEKEE	PING – good/ok/needs attention	
Storage of materials	good of the second secon	
Cleanliness		
Hygiene		
Escape routes/passages		
Cable management		
Slipping/tripping hazards		
Electrical Equipment Inspection and		
Testing		
Other		

Room no. JWS Level 6 staff toilet R635

FABRIC – General condition - good/ok/needs attention		
Lights	Light out above sink	
Heating		
Ventilation		
Floors/floor coverings		
Fire doors, doors and door furniture		
Electrical installation		
Sanitary Fittings		
Washing/Drying facilities		
Windows and window fittings		
Staircases, banisters and hand rails		
Furniture and fittings		
Other		
	DINC good/ok/poods attention	
HOUSEKEEPING – good/ok/needs attention		
Storage of materials Cleanliness		
Hygiene		
Escape routes/passages		
Cable management		
Slipping/tripping hazards		
Electrical Equipment Inspection and		
Testing		
Other		

Room no. JWS Level 7 Main Corridor R727, R727a

FABRIC – General condition - good/ok/needs attention	
Lights	1 off 4ft fluorescent tube needs replaced outside R718
Heating	
Ventilation	
Floors/floor coverings	
Fire doors, doors and door furniture	
Electrical installation	
Sanitary Fittings	
Washing/Drying facilities	
Windows and window fittings	
Staircases, banisters and hand rails	
Furniture and fittings	
Other	
	PING – good/ok/needs attention
Storage of materials	Lockers 731&732 overloaded with paper (fire accelerant)
	Storage of laboratory equipment outside R719 (temporary
Oleantiness	arrangement)
Cleanliness	
Hygiene	
Escape routes/passages	
Cable management	
Slipping/tripping hazards	
Electrical Equipment Inspection and	
Testing	
Other	

Room no. JWS Level 7 Side Corridor R727b

FABRIC – General condition - good/ok/needs attention		
Lights	1 off light out adjacent to R734	
Heating		
Ventilation		
Floors/floor coverings		
Fire doors, doors and door furniture		
Electrical installation		
Sanitary Fittings		
Washing/Drying facilities		
Windows and window fittings		
Staircases, banisters and hand rails		
Furniture and fittings		
Other		
HOUSEKEEPING – good/ok/needs attention		
Storage of materials	Excessive amount of periodicals on display or being stored (fire accelerant)	
Cleanliness		
Hygiene		
Escape routes/passages		
Cable management		
Slipping/tripping hazards		
Electrical Equipment Inspection and		
Testing		
Other		

Room no. JWS Level 8 corridor outside R817

FABRIC – General condition - good/ok/needs attention	
Lights	
Heating	
Ventilation	
Floors/floor coverings	
Fire doors, doors and door furniture	
Electrical installation	
Sanitary Fittings	
Washing/Drying facilities	
Windows and window fittings	
Staircases, banisters and hand rails	
Furniture and fittings	
Other	
	PING – good/ok/needs attention
Storage of materials	Corner needs cleared of equipment and clutter
	Hydraulic test equipment has sharp elements sticking out,
	requiresto be padded or relocated
Cleanliness	
Hygiene	
Escape routes/passages	
Cable management	
Slipping/tripping hazards	
Electrical Equipment Inspection and	
Testing	
Other	

Room no. JWS Level 8 corridor outside R802

FABRIC – General condition - good/ok/needs attention		
Lights		
Heating		
Ventilation		
Floors/floor coverings		
Fire doors, doors and door furniture	Fire door scuffing floor and staying open	
Electrical installation		
Sanitary Fittings		
Washing/Drying facilities		
Windows and window fittings		
Staircases, banisters and hand rails		
Furniture and fittings		
Other		
	PING – good/ok/needs attention	
Storage of materials Cleanliness		
Hygiene		
Escape routes/passages		
Cable management		
Slipping/tripping hazards		
Electrical Equipment Inspection and		
Testing Other		
Other		

Room no. JWS Level 8 R811 Staff Common Room

FABRIC – General condition - good/ok/needs attention		
Lights		
Heating		
Ventilation		
Floors/floor coverings		
Fire doors, doors and door furniture		
Electrical installation		
Sanitary Fittings		
Washing/Drying facilities		
Windows and window fittings		
Staircases, banisters and hand rails		
Furniture and fittings		
Other		
	PING – good/ok/needs attention	
Storage of materials		
Cleanliness		
Hygiene		
Escape routes/passages		
Cable management		
Slipping/tripping hazards		
Electrical Equipment Inspection and	Some PAT required	
Testing		
Other		