

SCHOOL OF ENGINEERING - BUILDING SAFETY AUDIT - FAULT REPORT SHEET

Please note that building audits provide a periodic overview of safety performance in the school and are supplementary to statutory inspections and other specific safety management procedures.

Building:		Audited by:	Date: 5/7/2013	
Room No	Room Function	Description of Fault	Urgent Y/N	Date Resolved
226A	BIO REACTOR LAB	NO PAT		
201A	STRUCTURAL LAB	NO PAT		
201C	OFFICE (TECH)	NO PAT.		
201A	TUNNELS.	TUNNEL 3 LIGHT OUT.		
225	MAT TESTING LAB	NO PAT.		
204	CONCRETE CORING LAB	NO PAT	YES	
202	CONCRETE TESTING LAB	NO PAT.		
205	WATER LAB	NO PAT - ELECT INSTALLATION UNSUIT FOR PURPOSES - NO PUSH BAR FIRE EXIT.		
224	PHOTOGRAPHY	NO PAT.		
222D	COMPUTER CLUSTER	NO PAT		
216A	ELEC DESIGN CENTRE PROTOTYPE LAB	NO PAT		
216	ELEC DESIGN CENTRE PROTOTYPE LAB	NO PAT		
213A	LABOR SUITE	SOCKET STRIP ROUND OPT TABLE W/ WOODS PAT		
212	LABOR LAB	SOME MAINS EXT NOT PAT + DAILY CHAINING		
210B	LABOR SUITE	SOCKET STRIP ROUND OPT TABLE. NO PAT		
133A	COMPUTER CLUSTER	NO PAT		
122	TERMINAL 2 BIO/ANO	SPLICES IN FLOOR @ ENTRANCE		
123	BAND	NO PAT		
120	TERMINAL 2	NO PAT		
114A	PLANT RM	NO PAT		
112	ULTRA SMALL LAB	NO PAT		
134E	U/S PLANT ROOM	NO PAT - OIL ON FLOOR		
134D	ACOUSTICS/OPTO	NO PAT.		
	CORRIDOR ADJ. ACOUSTICS	RUBBISH.		
109A	ELEC DESIGN CENTRE LAB 2	NO PAT.		
109	HW LAB 1	NO PAT.		
108	LEFT THEATRE	NO PAT		
107	"	"		
106	"	"		
134B	TOILET (F)	HAND DRIER - NO PAT 1ST LIGHT V. DIM.		

PLEASE RETURN FAULT REPORT SHEETS TO THE SCHOOL SAFETY COORDINATOR, ROOM 372 JAMES WATT SOUTH BUILDING

